



MASTER CONTROLLER SIDE VIEW

NOTE: RED CONNECTIONS ABOVE INDICATE ATTACHMENT OF TURN-SIGNAL INDICATORS